CTS

FLANGE USA™

CTS Venturi Flow Meter

Flow Charts

- Venturi Flow Meter 2 1/2
- Venturi Flow Meter 3“
- Venturi Flow Meter 4“
- Venturi Flow Meter 5“
- Venturi Flow Meter 6“
- Venturi Flow Meter 8“

CTS_venturi_flow_charts_04/23

Venturi Flow Meter 2 1/2"



Flow Chart 2 1/2"

Flow Coefficients Cv=43

For Exact GPM. Or △P

GPM = $\sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P = (GPM.x5.3/Cv)^2$

Venturi Flow Meter 3"



Flow Chart 3"

Flow Coefficients Cv=43

For Exact GPM. Or △P

$GPM = \sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P = (GPM.x5.3/Cv)^2$

Venturi Flow Meter 4"



Flow Chart 4"

Flow Coefficients Cv=43

For Exact GPM. Or △P

$GPM = \sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P = (GPM.x5.3/Cv)^2$

Venturi Flow Meter 5"



Flow Chart 5"

Flow Coefficients Cv=43

For Exact GPM. Or △P

GPM = $\sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P=(GPM.x5.3/Cv)^2$

Venturi Flow Meter 6"



Flow Chart 6"

Flow Coefficients Cv=43

For Exact GPM. Or △P

$GPM = \sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P = (GPM.x5.3/Cv)^2$

Venturi Flow Meter 8"



Flow Chart 8"

Flow Coefficients Cv=43

For Exact GPM. Or △P

GPM = $\sqrt{\triangle P} \times (Cv/5.3)$

$\triangle P=(GPM.x5.3/Cv)^2$